Contract No. EP/SP/66 Integrated Waste Mana	/12 gement Facilities, Phase 1	Keppel Seghers – Zhen Hua Joint Venture
Appendix N	Exceedance Report	

Statistical Summary of Exceedances in the Reporting Period

	Water Quality	(Regular Monitoring)	
Location	Action Level	Limit Level	Total
B1	0	1	1
B2	2	0	2
В3	0	0	0
B4	0	0	0
CR1	0	0	0
CR2	0	0	0
F1A	1	0	1
H1	0	0	0
S1		Not applicable	
S2A		Not applicable	
S3		Not applicable	
M1	0	0	0


	Noise (D	Oay Time)	
Location	Action Level	Limit Level	Total
M1	0	0	0
M2	0	0	0
M3	0	0	0
	Noise (Eve	ening Time)	
Location	Action Level	Limit Level	Total
M1	0	0	0
M2	0	0	0
M3	0	0	0
	Noise (N	ight Time)	
Location	Action Level	Limit Level	Total
M1	0	0	0
M2	0	0	0
М3	0	0	0

Incident Report on Action Level or Limit Level Non-compliance

Project	Integrated Waste Managemen	nt Facilities, Phase 1			
Date	06 Mar 2023 (Lab result rece	eived on 10 March 2023)			
Time	15:54 – 19:00 (Mid-Flood)				
Mid-Flood					
Monitoring Location	B1	B2 PROPOSED OUTFALL + 4 PROPOSED 132KV SUBMARINE CABLES B3 H1 SHEK KWU CHAU CR2 S3 CR1 PROPOSED RECLAIMED AREA FOR THE IMMF	F1A N F1A N N F1A M1 C2A Key A PROPOSED 132KV SUBMARINE CABLE MONITORING STATION PROPOSED OUTFALL THE IWMF SITE BOUNDARY LAND FORMATION FOOTPRINT THE IWMF SITE BOUNDARY		
Parameter	Suspended Solid (SS)				
Action & Limit Levels	Action Level	Limit Level			
	≥ 8.0 mg/L	≥ 10.0 mg/L			
Measurement Level	Impact Station(s) of	Control Stations	Impact Station(s) without		
	Exceedance		Exceedance		
	15.3 mg/L (B1)	3.7 mg/L (C1A) 2.8 mg/L (C2A)	5.0 mg/L (B2) 2.9 mg/L (B3) 4.0 mg/L (B4) 3.0 mg/L (H1) 3.2 mg/L (F1A) 4.1 mg/L (CR1) 3.9 mg/L (CR2) 3.6 mg/L (M1)		
Possible reason for Action or Limit Level Non-compliance	pile, piling works for pre-b seawall and existing caisson of Dominant sea current direction around Shek Kwu Chau. An exceedance of limit level of (neither upstream nor downs B1 is deemed to be unrelated	206 Mar 2023 include piling woored socketed H-pile, pile of extension, and Process Buildi on was found to be from Southwas found at B1. B1 is located stream, far away) to the works to the Project.	cap construction, blockwork ng construction works. theast to Northwest at waters at unrelated stream direction is location. An exceedance at		

According to the field observation by sampling team during sampling event, no silt plume was observed in the Project site and the weather was fine during the sampling event.
No major observation of improper site practices that contributed to the increase of the suspended solids was recorded during the weekly site inspection on 07 March 2023.
After the investigation, the exceedance on 06 March 2023 during flood tide at B1 is deemed to be unrelated to the Project.

Monitoring photos of stations with exceedance B1:




	Legend			
	Speed (knot)		Speed (knot)	
	0-0.5	\rightarrow	1.5-2.0	\rightarrow
	0.5-1.0	\rightarrow	2.0-2.5	\rightarrow
	1.0-1.5		2.5 and above	\rightarrow
	(Sourced from http://c	current.hy	dro.gov.hk/en/map.ht	ml)
Prepared by	Jack Chow			
Date	14 Mar 2023			

Incident Report on Action Level or Limit Level Non-compliance

Project	Integrated Waste Manageme	nt Facilities, Phase 1			
Date	08 Mar 2023 (Lab result rece	eived on 13 March 2023)			
Time	08:00 – 10:02 (Mid-Flood)				
	Mid-Flood				
Monitoring Location	B2 B1 S1	PROPOSED OUTFALL + A PROPOSED 133RV SUBMARINE CABLES B3 H1 SHEK KWU CHAU CR2 S3 CR1	F1A N F1A N N F1A N N N N N N N N N N N N N		
Parameter	Suspended Solid (SS)				
Action & Limit Levels	Action Level	Limit Leve	el		
	≥ 8.0 mg/L	≥ 10.0 mg/	/L		
Measurement Level	Impact Station(s) of	Control Stations	Impact Station(s) without		
	Exceedance		Exceedance		
	8.0 mg/L (B2)	3.8 mg/L (C1A)	5.6 mg/L (B1)		
		2.9 mg/L (C2A)	4.9 mg/L (B3)		
			2.8 mg/L (B4)		
			2.7 mg/L (F1A)		
			2.5 mg/L (H1)		
			2.8 mg/L (M1)		
			2.5 mg/L (CR1) 2.5 mg/L (CR2)		
			2.5 mg/L (CR2)		
Possible reason for Action or Limit Level Non-compliance	1 0 1				
	The installation of caisson Newas enclosed.	o.19 was completed on 18	Mar 2021, the reclamation area		

According to the field observation by sampling team during sampling event, no silt plume was observed in the Project site and the weather was fine during the sampling event.
No major observation of improper site practices that contributed to the increase of the suspended solids was recorded during the weekly site inspection on 14 March 2023.
After the investigation, the exceedance on 08 March 2023 during flood tide at B2 is deemed to be unrelated to the Project.

Monitoring photos of stations with exceedance B2:



	Legend			
	Speed (knot)		Speed (knot)	
	0-0.5	\rightarrow	1.5-2.0	\rightarrow
	0.5-1.0	\rightarrow	2.0-2.5	\rightarrow
	1.0-1.5		2.5 and above	\rightarrow
	(Sourced from http://c	current.hy	dro.gov.hk/en/map.ht	ml)
Prepared by	Jack Chow			
Date	22 Mar 2023			


Incident Report on Action Level or Limit Level Non-compliance

Project	Integrated Waste Managemen	nt Facilities, P	hase 1	
Date	20 Mar 2023 (Lab result rece	ived on 27 Ma	arch 2023)	
Time	10:09 – 13:39 (Mid-Ebb)			
	Mid-E	Ebb		
Monitoring Location	B2, F1A B10 S1-	PROPOSED OUTFALL + PROPOSED A PROPOSED A PROPOSED RECLAIM FOR THE IMME	H1 SHEK KWU CHAU CR2 S3 CR1	Key A PROPOSED 132KV SUBMARINE CABLE MONITORING STATION PROPOSED OUTFALL THE IWMF SITE BOUNDARY LAND FORMATION FOOTPRINT THE IWMF SITE BOUNDARY
Parameter	Suspended Solid (SS)			
Action & Limit Levels	Action Level		Limit Level	
	$\geq 8.0 \text{ mg/L}$		$\geq 10.0 \text{ mg/L}$	
Measurement Level	Impact Station(s) of Exceedance 8.3 mg/L (B2)	Control Stati	ions	Impact Station(s) without Exceedance 4.9 mg/L (B1)
	8.5 mg/L (F1A)	3.3 mg/L (C		4.3 mg/L (B3) 4.0 mg/L (B4) 4.8 mg/L (H1) 3.3 mg/L (M1) 7.5 mg/L (CR1) 4.8 mg/L (CR2)
Possible reason for Action or Limit Level Non-compliance	Works scheduled on site on 2 pile, piling works for pre-beseawall and existing caisson of Dominant sea current direction	ored socketed extension, and	H-pile, pile c Process Buildin	ap construction, blockwork ng construction works.
	around Shek Kwu Chau. Exceedances of action level unrelated stream direction (n location. Exceedances at B2 at the installation of caisson Nowas enclosed.	were found a either upstrea and F1A are d	at B2 and F1A. m nor downstre eemed to be uni	B2 and F1A are located at eam, far away) to the works related to the Project.

According to the field observation by sampling team during sampling event, no silt plume was observed in the Project site and the weather was overcast during the sampling event.
No major observation of improper site practices that contributed to the increase of the suspended solids was recorded during the weekly site inspection on 21 March 2023.
After the investigation, the exceedances on 20 March 2023 during ebb tide at B2 and F1A are deemed to be unrelated to the Project.

Keppel Seghers – Zhen Hua Joint Venture Monitoring photos of stations with exceedance B2:





	Legend			
	Speed (knot)		Speed (knot)	
	0-0.5	\rightarrow	1.5-2.0	\rightarrow
	0.5-1.0	\rightarrow	2.0-2.5	\rightarrow
	1.0-1.5		2.5 and above	\rightarrow
	(Sourced from http://c	current.hy	dro.gov.hk/en/map.ht	ml)
Prepared by	Jack Chow			
Date	30 Mar 2023			