

Appendix J Noise Monitoring Data

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N_S1)

Monitoring date: 2, 8, 14, 21, 28 October 2019 (Daytime)
 2&3, 8&9, 14&15, 21&22, 28&29 October 2019 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioning units nearby

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
2 Oct 2019	16:01	-	16:31	Sunny	45.0	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
2 Oct 2019	19:51	-	19:56	Fine	46.0	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	21:51	-	21:56		52.3		
	22:51	-	22:56		50.8		
3 Oct 2019	00:51	-	00:56	Fine	51.7	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	02:51	-	02:56		52.0		
	03:51	-	03:56		47.9		
8 Oct 2019	16:33	-	17:03	Sunny	63.1	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
8 Oct 2019	19:33	-	19:38	Fine	58.0	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	21:33	-	21:38		58.7		
	22:33	-	22:38		55.9		
9 Oct 2019	00:33	-	00:38	Fine	57.5	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	01:33	-	01:38		56.6		
	03:33	-	03:38		55.8		
14 Oct 2019	16:26	-	16:56	Sunny	50.9	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
14 Oct 2019	19:26	-	19:31	Fine	46.6	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	21:26	-	21:31		46.5		
	22:26	-	22:31		48.0		
15 Oct 2019	00:26	-	00:31	Fine	44.2	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	02:26	-	02:31		43.9		
	03:26	-	03:31		44.0		

Date	Start time		End time	Weather	L_{eq 30min} dB(A) / L_{eq 5min} dB(A)	Sound Level Meter Used	Calibrator Used
21 Oct 2019	16:32	-	17:02	Sunny	56.2	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
21 Oct 2019	19:32	-	19:37	Fine	53.6	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	21:32	-	21:37		54.7		
	22:32	-	22:37		53.2		
22 Oct 2019	00:32	-	00:37	Fine	49.2	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	02:32	-	02:37		47.5		
	03:32	-	03:37		45.8		
28 Oct 2019	16:33	-	17:03	Sunny	55.8	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
28 Oct 2019	19:33	-	19:38	Fine	52.0	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	21:33	-	21:38		50.8		
	22:33	-	22:38		52.4		
29 Oct 2019	00:33	-	00:38	Fine	51.3	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	02:33	-	02:38		51.6		
	03:33	-	03:38		49.3		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N_S2)

Monitoring date: 2, 8, 14, 21, 28 October 2019 (Daytime)

2&3, 8&9, 14&15, 21&22, 28&29 October 2019 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
2 Oct 2019	16:36	-	17:06	Sunny	59.7	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
2 Oct 2019	19:56	-	20:01	Fine	57.3	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	21:56	-	22:01		56.1		
	22:36	-	22:41		56.8		
3 Oct 2019	00:36	-	00:41	Fine	55.4	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	01:36	-	01:41		54.8		
	03:36	-	03:41		56.4		
8 Oct 2019	16:26	-	16:56	Sunny	58.8	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
8 Oct 2019	19:26	-	19:31	Fine	55.9	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	21:26	-	21:31		57.5		
	22:26	-	22:31		56.6		
9 Oct 2019	00:26	-	00:31	Fine	55.8	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	01:26	-	01:31		58.2		
	03:26	-	03:31		58.7		
14 Oct 2019	16:25	-	16:55	Sunny	53.2	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
14 Oct 2019	19:25	-	19:30	Fine	54.7	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	21:25	-	21:30		51.4		
	22:25	-	22:30		54.4		
15 Oct 2019	00:25	-	00:30	Fine	50.8	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	02:25	-	02:30		50.2		
	03:25	-	03:30		51.8		

Date	Start time		End time	Weather	L_{eq 30min} dB(A) / L_{eq 5min} dB(A)	Sound Level Meter Used	Calibrator Used
21 Oct 2019	16:32	-	17:02	Sunny	49.8	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
21 Oct 2019	19:32	-	19:37	Fine	52.2	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	21:32	-	21:37		51.3		
	22:32	-	22:37		47.5		
22 Oct 2019	00:32	-	00:37	Fine	48.0	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	02:32	-	02:37		47.9		
	03:32	-	03:37		48.5		
28 Oct 2019	16:32	-	17:02	Sunny	62.2	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
28 Oct 2019	19:32	-	19:37	Fine	59.1	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	21:32	-	21:37		49.9		
	22:32	-	22:37		59.9		
29 Oct 2019	00:32	-	00:37	Fine	49.5	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	02:32	-	02:37		58.9		
	03:32	-	03:37		60.1		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N_S3)

Monitoring date: 2, 8, 14, 21, 28 October 2019 (Daytime)

2&3, 8&9, 14&15, 21&22, 28&29 October 2019 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioning units nearby, dog barking

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
2 Oct 2019	16:33	-	17:03	Sunny	58.9	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
2 Oct 2019	19:33	-	19:38	Fine	55.4	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	21:33	-	21:38		55.6		
	22:33	-	22:38		57.0		
3 Oct 2019	00:33	-	00:38	Fine	55.9	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	02:33	-	02:38		52.9		
	03:33	-	03:38		53.9		
8 Oct 2019	16:36	-	17:06	Sunny	52.2	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
8 Oct 2019	19:36	-	19:41	Fine	51.6	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	21:36	-	21:41		48.9		
	22:36	-	22:41		47.9		
9 Oct 2019	00:36	-	00:41	Fine	47.6	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	01:36	-	01:41		51.0		
	03:36	-	03:41		47.4		
14 Oct 2019	16:29	-	17:59	Sunny	50.6	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
14 Oct 2019	19:29	-	19:34	Fine	48.9	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	21:29	-	21:34		48.1		
	22:29	-	22:34		47.4		
15 Oct 2019	00:29	-	00:34	Fine	44.5	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	02:29	-	02:34		44.2		
	03:29	-	03:34		44.5		

Date	Start time		End time	Weather	L_{eq 30min} dB(A) / L_{eq 5min} dB(A)	Sound Level Meter Used	Calibrator Used
21 Oct 2019	16:30	-	17:00	Sunny	54.0	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
21 Oct 2019	19:30	-	19:35	Fine	52.1	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	21:30	-	21:35		55.2		
	22:30	-	22:35		54.7		
22 Oct 2019	00:30	-	00:35	Fine	52.3	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	02:30	-	02:35		52.3		
	03:30	-	03:35		53.4		
28 Oct 2019	16:34	-	17:04	Sunny	55.9	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
28 Oct 2019	19:34	-	19:39	Fine	52.3	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	21:34	-	21:39		52.4		
	22:34	-	22:39		53.1		
29 Oct 2019	00:34	-	00:39	Fine	52.3	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	02:34	-	02:39		50.4		
	03:34	-	03:39		49.3		