

## Appendix J Noise Monitoring Data

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N\_S1)

Monitoring date: 4, 15, 18, 25 November 2019 (Daytime)  
 4&5, 15&16, 18&19, 25&26 November 2019 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
4 Nov 2019	16:01	-	16:31	Sunny	46.2	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
4 Nov 2019	19:31	-	19:36	Fine	38.5	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:31	-	20:36		46.7		
	21:31	-	21:36		48.4		
5 Nov 2019	1:31	-	01:36	Fine	41.2	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	2:31	-	02:36		39.7		
	4:31	-	04:36		40.2		
15 Nov 2019	16:08	-	16:38	Sunny	42.8	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
15 Nov 2019	19:38	-	19:43	Fine	44.4	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:38	-	20:43		39.8		
	21:38	-	21:43		39.9		
16 Nov 2019	1:38	-	01:43	Fine	44.6	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	2:38	-	02:43		39.7		
	4:38	-	04:43		39.5		
18 Nov 2019	16:03	-	16:33	Sunny	45.2	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
18 Nov 2019	19:33	-	19:38	Fine	45.8	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:33	-	20:38		47.4		
	21:33	-	21:38		47.3		
19 Nov 2019	1:33	-	01:38	Fine	44.9	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	2:33	-	02:38		40.9		
	4:33	-	04:38		39.5		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b>L<sub>eq 30min</sub> dB(A) / L<sub>eq 5min</sub> dB(A)</b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
25 Nov 2019	16:03	-	16:33	Sunny	59.7	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
25 Nov 2019	19:08	-	19:13	Fine	58.9	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:08	-	20:13		56.7		
	21:08	-	21:13		57.6		
26 Nov 2019	1:08	-	01:13	Fine	48.4	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	3:08	-	03:13		48.7		
	5:08	-	05:13		49.2		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N\_S2)

Monitoring date: 4, 15, 18, 25 November 2019 (Daytime)  
 4&5, 15&16, 18&19, 25&26 November 2019 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
4 Nov 2019	16:06	-	16:36	Sunny	41.7	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
4 Nov 2019	19:36	-	19:41	Fine	40.9	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	20:36	-	20:41		46.3		
	21:36	-	21:41		47.3		
5 Nov 2019	1:36	-	01:41	Fine	41.3	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	2:36	-	02:41		39.0		
	4:36	-	04:41		40.8		
15 Nov 2019	16:07	-	16:37	Sunny	60.4	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
15 Nov 2019	19:32	-	19:37	Fine	60.8	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	20:32	-	20:37		59.7		
	21:32	-	21:37		60.0		
16 Nov 2019	1:32	-	01:37	Fine	58.5	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	2:32	-	02:37		55.2		
	4:32	-	04:37		55.2		
18 Nov 2019	16:09	-	16:39	Sunny	61.8	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
18 Nov 2019	19:39	-	19:44	Fine	65.1	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	20:39	-	20:44		61.8		
	21:39	-	21:44		61.6		
19 Nov 2019	1:39	-	01:44	Fine	59.7	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	2:39	-	02:44		57.0		
	4:39	-	04:44		54.8		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b>L<sub>eq 30min</sub> dB(A) / L<sub>eq 5min</sub> dB(A)</b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
25 Nov 2019	16:03	-	16:33	Sunny	58.9	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
25 Nov 2019	19:08	-	19:13	Fine	59.3	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
	20:08	-	20:13		59.8		
	21:08	-	21:13		60.3		
26 Nov 2019	1:08	-	01:13	Fine	60.9	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
	3:08	-	03:13		55.0		
	5:08	-	05:13		54.1		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N\_S3)

Monitoring date: 4, 15, 18, 25 November 2019 (Daytime)  
 4&5, 15&16, 18&19, 25&26 November 2019 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioning units nearby, dog barking

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
4 Nov 2019	16:05	-	16:35	Sunny	55.5	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
4 Nov 2019	19:35	-	19:40	Fine	49.7	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:35	-	20:40		50.6		
	21:35	-	21:40		48.5		
5 Nov 2019	1:35	-	01:40	Fine	46.8	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	2:35	-	02:40		48.0		
	4:35	-	04:40		47.0		
15 Nov 2019	16:06	-	16:36	Sunny	51.4	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
15 Nov 2019	19:36	-	19:41	Fine	50.9	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:36	-	20:41		50.3		
	21:36	-	21:41		50.5		
16 Nov 2019	1:36	-	01:41	Fine	49.5	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	2:36	-	02:41		50.7		
	4:36	-	04:41		48.8		
18 Nov 2019	16:09	-	16:39	Sunny	54.4	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
18 Nov 2019	19:39	-	19:44	Fine	53.4	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:39	-	20:44		53.5		
	21:39	-	21:44		55.4		
19 Nov 2019	1:39	-	01:44	Fine	52.5	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	2:39	-	02:44		53.0		
	4:39	-	04:44		51.9		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b>L<sub>eq 30min</sub> dB(A) / L<sub>eq 5min</sub> dB(A)</b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
25 Nov 2019	16:04	-	16:34	Sunny	54.9	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
25 Nov 2019	19:09	-	19:14	Fine	54.0	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:09	-	20:14		52.1		
	21:09	-	21:14		53.5		
26 Nov 2019	1:09	-	01:14	Fine	52.5	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	3:09	-	03:14		51.4		
	5:09	-	05:14		50.7		