

## Appendix J Noise Monitoring Data

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N\_S1)

Monitoring date: 2, 9, 16, 23 & 30 December 2019 (Daytime)  
 2&3, 9&10, 16&17, 23&24, 30&31 December 2019 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
2 Dec 2019	16:07	-	16:37	Sunny	59.3	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
2 Dec 2019	19:12	-	19:17	Fine	52.3	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:12	-	20:17		55.2		
	21:12	-	21:17		51.1		
3 Dec 2019	1:12	-	01:17	Fine	47.3	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	3:12	-	03:17		51.6		
	5:12	-	05:17		56.1		
9 Dec 2019	16:04	-	16:34	Sunny	55.4	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
9 Dec 2019	19:14	-	19:19	Fine	53.4	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:14	-	20:19		53.9		
	21:14	-	21:19		57.8		
10 Dec 2019	1:14	-	01:19	Fine	50.4	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	3:14	-	03:19		47.9		
	5:14	-	05:19		49.3		
16 Dec 2019	16:15	-	16:45	Sunny	59.5	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
16 Dec 2019	19:15	-	19:20	Fine	53.5	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:15	-	20:20		56.1		
	21:15	-	21:20		56.7		
17 Dec 2019	1:15	-	01:20	Fine	56.7	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	3:15	-	03:20		56.2		
	5:15	-	05:20		54.5		

Date	Start time		End time	Weather	$L_{eq\ 30min\ dB(A)} / L_{eq\ 5min\ dB(A)}$	Sound Level Meter Used	Calibrator Used
23 Dec 2019	16:14	-	16:44	Sunny	57.3	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
23 Dec 2019	19:14	-	19:19	Fine	57.5	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:14	-	20:19		56.4		
	21:14	-	21:19		56.3		
24 Dec 2019	1:14	-	01:19	Fine	57.3	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	3:14	-	03:19		52.7		
	5:14	-	05:19		50.7		
30 Dec 2019	16:10	-	16:40	Sunny	56.7	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
30 Dec 2019	19:10	-	19:15	Fine	58.0	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	20:10	-	20:15		59.6		
	21:10	-	21:15		58.8		
31 Dec 2019	1:10	-	01:15	Fine	47.5	XL2 (Serial No. A2A-13548-E0)	SV33B (No. 83042)
	3:10	-	03:15		47.9		
	5:10	-	05:15		48.2		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N\_S2)

Monitoring date: 2, 9, 16, 23 & 30 December 2019 (Daytime)  
2&3, 9&10, 16&17, 23&24, 30&31 December 2019 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
2 Dec 2019	16:02	-	16:32	Sunny	57.3	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
2 Dec 2019	19:12	-	19:17	Fine	54.8	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
	20:12	-	20:17		56.0		
	21:12	-	21:17		58.1		
3 Dec 2019	1:12	-	01:17	Fine	51.0	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
	3:12	-	03:17		53.1		
	5:12	-	05:17		60.1		
9 Dec 2019	16:06	-	16:36	Sunny	56.3	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
9 Dec 2019	19:16	-	19:21	Fine	53.3	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	20:16	-	20:21		54.0		
	21:16	-	21:21		53.7		
10 Dec 2019	1:16	-	01:21	Fine	50.2	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	3:16	-	03:21		49.8		
	5:16	-	05:21		52.5		
16 Dec 2019	16:15	-	16:45	Sunny	58.8	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
16 Dec 2019	19:15	-	19:20	Fine	53.5	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
	20:15	-	20:20		55.1		
	21:15	-	21:20		54.0		
17 Dec 2019	1:15	-	01:20	Fine	56.1	XL2 (Serial No. A2A-13663-E0)	SV33B (No. 83042)
	3:15	-	03:20		58.9		
	5:15	-	05:20		55.6		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b>L<sub>eq 30min</sub> dB(A) / L<sub>eq 5min</sub> dB(A)</b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
23 Dec 2019	16:19	-	16:49	Sunny	58.6	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
23 Dec 2019	19:19	-	19:24	Fine	56.7	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	20:19	-	20:24		55.6		
	21:19	-	21:24		54.8		
24 Dec 2019	1:19	-	01:24	Fine	56.6	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	3:19	-	03:24		52.8		
	5:19	-	05:24		50.4		
30 Dec 2019	16:07	-	16:37	Sunny	53.4	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
30 Dec 2019	19:07	-	19:12	Fine	51.4	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	20:07	-	20:12		53.7		
	21:07	-	21:12		52.6		
31 Dec 2019	1:07	-	01:12	Fine	49.5	XL2 (Serial No. A2A-13661-E0)	SV33B (No. 83042)
	3:07	-	03:12		50.5		
	5:07	-	05:12		49.1		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N\_S3)

Monitoring date: 2, 9, 16, 23 & 30 December 2019 (Daytime)  
 2&3, 9&10, 16&17, 23&24, 30&31 December 2019 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
2 Dec 2019	16:04	-	16:34	Sunny	58.0	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
2 Dec 2019	19:14	-	19:19	Fine	52.2	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:14	-	20:19		54.1		
	21:14	-	21:19		57.6		
3 Dec 2019	1:14	-	01:19	Fine	54.2	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	3:14	-	03:19		48.6		
	5:14	-	05:19		51.1		
9 Dec 2019	16:07	-	16:37	Sunny	55.8	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
9 Dec 2019	19:17	-	19:22	Fine	51.2	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:17	-	20:22		54.9		
	21:17	-	21:22		54.3		
10 Dec 2019	1:17	-	01:22	Fine	48.8	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	3:17	-	03:22		51.3		
	5:17	-	05:22		52.0		
16 Dec 2019	16:14	-	16:44	Sunny	57.4	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
16 Dec 2019	19:14	-	19:19	Fine	55.1	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:14	-	20:19		56.7		
	21:14	-	21:19		50.9		
17 Dec 2019	1:14	-	01:19	Fine	47.4	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	3:14	-	03:19		51.8		
	5:14	-	05:19		48.5		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b>L<sub>eq 30min</sub> dB(A) / L<sub>eq 5min</sub> dB(A)</b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
23 Dec 2019	16:07	-	16:37	Sunny	51.6	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
23 Dec 2019	19:07	-	19:12	Fine	56.3	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	20:07	-	20:12		57.0		
	21:07	-	21:12		51.2		
24 Dec 2019	1:07	-	01:12	Fine	49.0	SVAN 971 (Serial No. 77731)	SV33B (No. 83042)
	3:07	-	03:12		47.4		
	5:07	-	05:12		45.6		