



Appendix D Noise Monitoring Data Trending

Impact Noise Monitoring Results during Day Time (0700 - 1900 hours)



Additional Impact Noise Monitoring Results during Night Time (2300 - 0700 hours)



Summary of the Construction Activities Undertaken during the Reporting Period

Location of works	Construction activities undertaken	Remarks on progress
Reclamation area	<ul style="list-style-type: none"> • Reclamation works • Installation of Instrumentation • Site Investigation works for foundation • Foundation works (including Driven H Pile and Socketed H Pile) • Pile cap construction • Structural steel work 	<ul style="list-style-type: none"> • Completed • On-going • On-going • On-going • On-going • On-going
Seawall portion	<ul style="list-style-type: none"> • Installation of Chinese Pod • Caisson extension works, from +3mPD to +6mPD, at Seawall A and B • Construction of wave wall along the vertical seawall 	<ul style="list-style-type: none"> • Completed • On-going • On-going

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N_S1)

Monitoring date: 04, 09, 16, 26, 30 January 2023 (Daytime)

04&05, 09&10, 16&17, 26&27, 30&31 January 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
04 Jan 2023	13:33	-	14:03	Cloudy	59.4	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
04 Jan 2023	19:13	-	19:18	Fine	46.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	20:23	-	20:28		43.0		
	21:08	-	21:13		41.3		
05 Jan 2023	1:23	-	1:28	Fine	39.8	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	3:13	-	3:18		41.4		
	5:18	-	5:23		39.7		
09 Jan 2023	13:04	-	13:34	Cloudy	59.6	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
09 Jan 2023	19:24	-	19:29	Fine	44.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	20:24	-	20:29		42.3		
	21:24	-	21:29		41.0		
10 Jan 2023	1:24	-	1:29	Fine	39.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:14	-	3:19		41.5		
	5:09	-	5:14		39.7		
16 Jan 2023	13:09	-	13:39	Cloudy	62.4	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
16 Jan 2023	19:29	-	19:34	Fine	40.6	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	20:19	-	20:24		42.6		
	21:19	-	21:24		42.1		
17 Jan 2023	1:24	-	1:29	Fine	41.2	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	3:24	-	3:29		43.1		
	5:39	-	5:44		37.9		
26 Jan 2023	13:16	-	13:46	Fine	48.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
26 Jan 2023	19:21	-	19:26	Fine	44.6	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	20:06	-	20:11		41.9		
	21:16	-	21:21		39.3		
27 Jan 2023	1:06	-	1:11	Fine	36.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	3:11	-	3:16		37.8		
	5:16	-	5:21		39.7		
30 Jan 2023	13:16	-	13:46	Sunny	60.8	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)

Date	Start time		End time	Weather	L_{eq 30min} dB(A) / L_{eq 5min} dB(A)	Sound Level Meter Used	Calibrator Used
30 Jan 2023	19:26	-	19:31	Fine	44.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	20:21	-	20:26		42.9		
	21:36	-	21:41		40.1		
31 Jan 2023	1:21	-	1:26	Fine	38.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724243)
	3:11	-	3:16		38.6		
	5:11	-	5:16		40.5		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N_S1)

Monitoring date: 06, 13, 20, 27 February 2023 (Daytime)

06&07, 13&14, 20&21, 27&28 February 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Feb 2023	13:18	-	13:48	Sunny	59.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
06 Feb 2023	19:13	-	19:18	Fine	43.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:08	-	20:13		47.8		
	21:08	-	21:13		42.2		
07 Feb 2023	1:18	-	1:23	Fine	40.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:23	-	3:28		40.3		
	5:28	-	5:33		38.3		
13 Feb 2023	13:47	-	14:17	Sunny	59.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
13 Feb 2023	19:17	-	19:22	Fine	49.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:27	-	20:32		45.7		
	21:22	-	21:27		43.6		
14 Feb 2023	1:17	-	1:22	Fine	40.2	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:17	-	3:22		35.1		
	5:22	-	5:27		40.4		
20 Feb 2023	13:53	-	14:23	Sunny	64.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
20 Feb 2023	19:18	-	19:23	Fine	42.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:13	-	20:18		52.8		
	21:28	-	21:33		43.6		
21 Feb 2023	1:13	-	1:18	Sunny	46.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:18	-	3:23		44.3		
	5:18	-	5:23		41.8		
27 Feb 2023	13:34	-	14:04	Fine	61.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
27 Feb 2023	19:29	-	19:34	Fine	62.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:24	-	20:29		50.1		
	21:29	-	21:34		42.5		
28 Feb 2023	1:09	-	1:14	Fine	45.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:19	-	3:24		41.7		
	5:14	-	5:19		41.1		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N_S1)

Monitoring date: 06, 16, 20, 27 March 2023 (Daytime)

06&07, 16&17, 20&21, 27&28 March 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Mar 2023	13:44	-	14:14	Sunny	61.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
06 Mar 2023	19:14	-	19:19	Fine	51.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:29	-	20:34		51.2		
	21:34	-	21:39		51.4		
07 Mar 2023	1:09	-	1:14	Fine	51.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:19	-	3:24		51.8		
	5:19	-	5:24		48.5		
16 Mar 2023	13:58	-	14:28	Sunny	59.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
16 Mar 2023	19:18	-	19:23	Fine	45.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:03	-	20:08		44.7		
	21:18	-	21:23		44.8		
17 Mar 2023	1:28	-	1:33	Fine	45.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:23	-	3:28		50.9		
	5:18	-	5:23		51.0		
20 Mar 2023	13:36	-	14:06	Fine	61.1	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
20 Mar 2023	19:11	-	19:16	Fine	48.4	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:06	-	20:11		48.3		
	21:26	-	21:31		48.6		
21 Mar 2023	1:26	-	1:31	Cloudy	46.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:26	-	3:31		46.1		
	5:26	-	5:31		48.2		
27 Mar 2023	13:35	-	14:05	Fine	58.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
27 Mar 2023	19:20	-	19:25	Fine	46.2	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:20	-	20:25		42.6		
	21:10	-	21:15		43.6		
28 Mar 2023	1:15	-	1:20	Fine	39.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:25	-	3:30		40.3		
	5:20	-	5:25		40.9		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N_S2)

Monitoring date: 04, 09, 16, 26, 30 January 2023 (Daytime)

04&05, 09&10, 16&17, 26&27, 30&31 January 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
04 Jan 2023	13:41	-	14:11	Cloudy	56.2	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
04 Jan 2023	19:11	-	19:16	Fine	45.5	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	20:16	-	20:21		46.4		
	21:11	-	21:16		50.7		
05 Jan 2023	1:16	-	1:21	Fine	43.4	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	3:06	-	3:11		42.9		
	5:11	-	5:16		43.3		
09 Jan 2023	13:17	-	13:47	Cloudy	55.7	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
09 Jan 2023	19:22	-	19:27	Fine	48.2	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	20:27	-	20:32		50.5		
	21:22	-	21:27		46.8		
10 Jan 2023	1:22	-	1:27	Fine	46.4	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	3:17	-	3:22		48.6		
	5:07	-	5:12		46.8		
16 Jan 2023	13:20	-	13:50	Cloudy	58.0	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
16 Jan 2023	19:15	-	19:20	Fine	48.7	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	20:10	-	20:15		50.0		
	21:25	-	21:30		46.3		
17 Jan 2023	1:25	-	1:30	Fine	47.3	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	3:25	-	3:30		48.7		
	5:25	-	5:30		44.8		
26 Jan 2023	13:19	-	13:49	Fine	50.0	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
26 Jan 2023	19:34	-	19:39	Fine	48.4	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	20:29	-	20:34		48.2		
	21:34	-	21:39		47.6		
27 Jan 2023	1:19	-	1:24	Fine	47.4	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	3:09	-	3:14		51.2		
	5:14	-	5:19		51.8		
30 Jan 2023	13:31	-	14:01	Sunny	57.3	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)

Date	Start time		End time	Weather	L_{eq 30min} dB(A) / L_{eq 5min} dB(A)	Sound Level Meter Used	Calibrator Used
30 Jan 2023	19:26	-	19:31	Fine	48.2	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	20:46	-	20:51		45.4		
	21:46	-	21:51		45.6		
31 Jan 2023	1:26	-	1:31	Fine	47.5	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724243)
	3:16	-	3:21		48.8		
	5:21	-	5:26		48.0		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N_S2)

Monitoring date: 06, 13, 20, 27 February 2023 (Daytime)

06&07, 13&14, 20&21, 27&28 February 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Feb 2023	13:28	-	13:58	Sunny	56.0	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
06 Feb 2023	19:08	-	19:13	Fine	51.4	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	20:28	-	20:33		47.1		
	21:08	-	21:13		45.6		
07 Feb 2023	1:13	-	1:18	Fine	44.5	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	3:28	-	3:33		44.4		
	5:18	-	5:23		43.7		
13 Feb 2023	13:33	-	14:03	Sunny	58.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
13 Feb 2023	19:08	-	19:13	Fine	47.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	20:23	-	20:28		48.2		
	21:18	-	21:23		53.7		
14 Feb 2023	1:28	-	1:33	Fine	49.3	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	3:23	-	3:28		44.7		
	5:23	-	5:28		54.3		
20 Feb 2023	13:38	-	14:08	Sunny	58.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
20 Feb 2023	19:13	-	19:18	Fine	51.3	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	20:13	-	20:18		48.2		
	21:23	-	21:28		49.6		
21 Feb 2023	1:23	-	1:28	Sunny	55.4	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	3:13	-	3:18		49.1		
	5:23	-	5:28		48.4		
27 Feb 2023	13:14	-	13:44	Fine	56.9	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
27 Feb 2023	19:19	-	19:24	Fine	58.0	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	20:29	-	20:34		52.3		
	21:34	-	21:39		51.1		
28 Feb 2023	1:14	-	1:19	Fine	56.3	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	3:24	-	3:29		50.6		
	5:14	-	5:19		50.1		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N_S2)

Monitoring date: 06, 16, 20, 27 March 2023 (Daytime)

06&07, 16&17, 20&21, 27&28 March 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Mar 2023	13:49	-	14:19	Sunny	57.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
06 Mar 2023	19:14	-	19:19	Fine	52.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	20:29	-	20:34		53.7		
	21:24	-	21:29		51.6		
07 Mar 2023	1:14	-	1:19	Fine	51.2	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	3:24	-	3:29		51.3		
	5:24	-	5:29		49.4		
16 Mar 2023	13:40	-	14:10	Sunny	57.1	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
16 Mar 2023	19:15	-	19:20	Fine	51.0	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	20:05	-	20:10		50.3		
	21:15	-	21:20		50.8		
17 Mar 2023	1:20	-	1:25	Fine	49.4	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	3:25	-	3:30		51.0		
	5:25	-	5:30		49.7		
20 Mar 2023	13:47	-	14:17	Fine	56.7	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
20 Mar 2023	19:12	-	19:17	Fine	50.5	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	20:07	-	20:12		49.4		
	21:27	-	21:32		50.3		
21 Mar 2023	1:27	-	1:32	Cloudy	48.9	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	3:27	-	3:32		48.7		
	5:27	-	5:32		48.6		
27 Mar 2023	13:42	-	14:12	Fine	57.5	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
27 Mar 2023	19:22	-	19:27	Fine	50.7	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	20:22	-	20:27		50.0		
	21:07	-	21:12		49.6		
28 Mar 2023	1:12	-	1:17	Fine	49.6	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	3:27	-	3:32		49.7		
	5:22	-	5:27		49.7		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N_S3)

Monitoring date: 04, 09, 16, 26, 30 January 2023 (Daytime)

04&05, 09&10, 16&17, 26&27, 30&31 January 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
04 Jan 2023	13:40	-	14:10	Cloudy	56.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
04 Jan 2023	19:10	-	19:15	Fine	48.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	20:20	-	20:25		43.3		
	21:05	-	21:10		41.2		
05 Jan 2023	1:15	-	1:20	Fine	46.8	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	3:10	-	3:15		41.0		
	5:15	-	5:20		42.8		
09 Jan 2023	13:27	-	13:57	Cloudy	61.4	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
09 Jan 2023	19:27	-	19:32	Fine	42.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	20:12	-	20:17		50.5		
	21:17	-	21:22		42.3		
10 Jan 2023	1:22	-	1:27	Fine	43.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	3:17	-	3:22		49.4		
	5:12	-	5:17		43.8		
16 Jan 2023	13:31	-	14:01	Cloudy	65.6	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
16 Jan 2023	19:11	-	19:16	Fine	42.1	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	20:06	-	20:11		40.9		
	21:16	-	21:21		40.4		
17 Jan 2023	1:01	-	1:06	Fine	40.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	3:31	-	3:36		39.0		
	5:06	-	5:11		38.0		
26 Jan 2023	13:23	-	13:53	Fine	48.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
26 Jan 2023	19:08	-	19:13	Fine	42.1	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	20:13	-	20:18		44.6		
	21:23	-	21:28		41.1		
27 Jan 2023	1:33	-	1:38	Fine	36.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	3:23	-	3:28		36.4		
	5:18	-	5:23		45.6		
30 Jan 2023	13:38	-	14:08	Sunny	56.5	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)

Date	Start time		End time	Weather	L_{eq 30min} dB(A) / L_{eq 5min} dB(A)	Sound Level Meter Used	Calibrator Used
30 Jan 2023	19:23	-	19:28	Fine	43.8	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	20:23	-	20:28		44.0		
	21:23	-	21:28		42.9		
31 Jan 2023	1:18	-	1:23	Fine	42.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724243)
	3:13	-	3:18		43.5		
	5:23	-	5:28		43.1		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N_S3)

Monitoring date: 06, 13, 20, 27 February 2023 (Daytime)

06&07, 13&14, 20&21, 27&28 February 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Feb 2023	13:24	-	13:54	Sunny	58.9	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
06 Feb 2023	19:09	-	19:14	Fine	43.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:14	-	20:19		43.2		
	21:24	-	21:29		47.2		
07 Feb 2023	1:19	-	1:24	Fine	44.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:14	-	3:19		43.0		
	5:14	-	5:19		39.2		
13 Feb 2023	13:19	-	13:49	Sunny	55.5	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
13 Feb 2023	19:14	-	19:19	Fine	48.4	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:24	-	20:29		50.0		
	21:19	-	21:24		48.9		
14 Feb 2023	1:14	-	1:19	Fine	39.2	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:09	-	3:14		39.4		
	5:14	-	5:19		43.4		
20 Feb 2023	13:12	-	13:42	Sunny	57.2	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
20 Feb 2023	19:12	-	19:17	Fine	49.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:12	-	20:17		43.7		
	21:32	-	21:37		44.3		
21 Feb 2023	1:17	-	1:22	Sunny	52.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:22	-	3:27		49.9		
	5:22	-	5:27		47.0		
27 Feb 2023	13:37	-	14:07	Fine	57.1	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
27 Feb 2023	19:22	-	19:27	Fine	49.5	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:12	-	20:17		48.2		
	21:07	-	21:12		45.5		
28 Feb 2023	1:07	-	1:12	Fine	48.5	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:12	-	3:17		47.0		
	5:07	-	5:12		44.7		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N_S3)

Monitoring date: 06, 16, 20, 27 March 2023 (Daytime)

06&07, 16&17, 20&21, 27&28 March 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Mar 2023	13:43	-	14:13	Sunny	57.9	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
06 Mar 2023	19:13	-	19:18	Fine	46.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:28	-	20:33		47.5		
	21:33	-	21:38		46.9		
07 Mar 2023	1:13	-	1:18	Fine	47.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:03	-	3:08		47.3		
	5:08	-	5:13		43.6		
16 Mar 2023	13:33	-	14:03	Sunny	54.6	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
16 Mar 2023	19:13	-	19:18	Fine	45.1	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:08	-	20:13		42.0		
	21:23	-	21:28		41.3		
17 Mar 2023	1:18	-	1:23	Fine	45.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:18	-	3:23		48.1		
	5:18	-	5:23		44.3		
20 Mar 2023	13:02	-	13:32	Fine	54.8	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
20 Mar 2023	19:07	-	19:12	Fine	46.4	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:07	-	20:12		44.7		
	21:27	-	21:32		49.0		
21 Mar 2023	1:22	-	1:27	Cloudy	43.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:12	-	3:17		39.5		
	5:07	-	5:12		43.3		
27 Mar 2023	13:38	-	14:08	Fine	59.2	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
27 Mar 2023	19:23	-	19:28	Fine	44.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:23	-	20:28		43.6		
	21:23	-	21:28		40.6		
28 Mar 2023	1:18	-	1:23	Fine	43.4	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:23	-	3:28		45.9		
	5:23	-	5:28		46.3		