



## Appendix C Noise Monitoring Data Trending


### Impact Noise Monitoring Results during Day Time (0700 - 1900 hours)



# Additional Impact Noise Monitoring Results during Evening Time (1900 - 2300 hours)



### Additional Impact Noise Monitoring Results during Night Time (2300 - 0700 hours)



**Summary of the Construction Activities Undertaken during the Reporting Period**

<b>Location of works</b>	<b>Construction activities undertaken</b>	<b>Remarks on progress</b>
Reclamation area	<ul style="list-style-type: none"> <li>• Installation of Instrumentation</li> <li>• Site Investigation works for foundation</li> <li>• Foundation works (including Driven H Pile and Socketed H Pile)</li> <li>• Pile cap construction</li> <li>• Structural steel work</li> <li>• Superstructure construction</li> </ul>	<ul style="list-style-type: none"> <li>• On-going</li> <li>• On-going</li> <li>• On-going</li> <li>• On-going</li> <li>• On-going</li> <li>• On-going</li> </ul>
Seawall portion	<ul style="list-style-type: none"> <li>• Caisson extension works, from +3mPD to +6mPD, at Seawall A and B</li> <li>• Construction of wave wall along the vertical seawall</li> </ul>	<ul style="list-style-type: none"> <li>• On-going</li> <li>• On-going</li> </ul>

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N\_S1)

Monitoring date: 03, 10, 20, 26 July 2023 (Daytime)

03&04, 10&11, 20&21, 26&27 July 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
03 July 2023	13:35	-	14:05	Sunny	61.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
03 July 2023	19:30	-	19:35	Fine	54.0	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:20	-	20:25		52.4		
	21:20	-	21:25		52.2		
04 July 2023	1:25	-	1:30	Fine	49.0	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:30	-	3:35		50.0		
	5:25	-	5:30		51.4		
10 July 2023	13:47	-	14:17	Sunny	63.9	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
10 July 2023	19:27	-	19:32	Fine	50.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:22	-	20:27		50.9		
	21:22	-	21:27		52.1		
11 July 2023	1:22	-	1:27	Fine	49.5	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:27	-	3:32		49.9		
	5:22	-	5:27		51.3		
20 July 2023	13:51	-	14:21	Sunny	60.5	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
20 July 2023	19:11	-	19:16	Fine	49.6	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:16	-	20:21		55.6		
	21:11	-	21:16		52.4		
21 July 2023	1:11	-	1:16	Fine	51.4	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:16	-	3:21		49.7		
	5:26	-	5:31		51.2		
26 July 2023	13:40	-	14:10	Sunny	65.4	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
26 July 2023	19:20	-	19:25	Fine	51.9	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:20	-	20:25		53.2		
	21:20	-	21:25		51.6		
27 July 2023	1:15	-	1:20	Fine	49.1	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:15	-	3:20		49.0		
	5:30	-	5:35		49.5		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N\_S1)

Monitoring date: 01, 07, 14, 21, 28 August 2023 (Daytime)

01&02, 07&08, 14&15, 21&22 and 28&29 August 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
01 Aug 2023	13:46	-	14:16	Fine	62.2	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
01 Aug 2023	19:06	-	19:11	Fine	47.7	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:16	-	20:21		51.5		
	21:26	-	21:31		50.8		
02 Aug 2023	1:11	-	1:16	Fine	49.0	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:31	-	3:36		48.1		
	5:16	-	5:21		49.1		
07 Aug 2023	13:41	-	14:11	Cloudy	61.8	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
07 Aug 2023	19:16	-	19:21	Fine	55.5	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:21	-	20:26		53.5		
	21:31	-	21:36		52.1		
08 Aug 2023	1:16	-	1:21	Fine	47.8	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:36	-	3:41		48.2		
	5:06	-	5:11		49.2		
14 Aug 2023	13:48	-	14:18	Fine	57.1	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
14 Aug 2023	19:23	-	19:28	Fine	51.1	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:18	-	20:23		51.0		
	21:13	-	21:18		50.8		
15 Aug 2023	1:18	-	1:23	Fine	48.9	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:08	-	3:13		48.4		
	5:08	-	5:13		49.8		
21 Aug 2023	14:47	-	15:17	Fine	60.9	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
22 Aug 2023	19:07	-	19:12	Fine	52.7	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:27	-	20:32		54.0		
	21:07	-	21:12		55.0		
22 Aug 2023	1:12	-	1:17	Fine	50.5	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:17	-	3:22		51.6		
	5:17	-	5:22		51.8		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b>L<sub>eq 30min</sub> dB(A) / L<sub>eq 5min</sub> dB(A)</b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
28 Aug 2023	14:00	-	14:30	Sunny	57.8	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
28 Aug 2023	19:20	-	19:25	Fine	52.3	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:25	-	20:30		51.5		
	21:30	-	21:35		53.3		
29 Aug 2023	1:15	-	1:20	Fine	50.4	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:15	-	3:20		49.3		
	5:20	-	5:25		50.6		



Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N\_S1)

Monitoring date: 06, 15, 19, 25 September 2023 (Daytime)

06&15, 15&16, 19&20 and 25&26 September 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Sep 2023	14:16	-	14:46	Cloudy	59.4	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
06 Sep 2023	19:16	-	19:21	Fine	51.2	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:26	-	20:31		50.8		
	21:16	-	21:21		51.6		
07 Sep 2023	1:36	-	1:41	Fine	48.1	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:46	-	3:51		48.2		
	5:31	-	5:36		50.6		
15 Sep 2023	13:24	-	13:54	Cloudy	59.7	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
15 Sep 2023	19:19	-	19:24	Fine	47.8	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:14	-	20:19		48.1		
	20:49	-	20:54		48.0		
16 Sep 2023	1:34	-	1:39	Fine	46.4	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:19	-	3:24		47.5		
	5:19	-	5:24		47.5		
19 Sep 2023	13:29	-	13:59	Sunny	58.1	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
19 Sep 2023	19:24	-	19:29	Fine	49.8	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:19	-	20:24		49.6		
	22:14	-	22:19		49.1		
20 Sep 2023	1:14	-	1:19	Fine	49.4	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:29	-	3:34		48.5		
	5:24	-	5:29		47.8		
25 Sep 2023	13:50	-	14:20	Sunny	57.8	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124528)
25 Sep 2023	19:25	-	19:30	Fine	51.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124528)
	20:15	-	20:20		53.1		
	21:10	-	21:15		51.8		
26 Sep 2023	1:30	-	1:35	Fine	48.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124528)
	3:15	-	3:20		48.1		
	5:20	-	5:25		48.0		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N\_S2)

Monitoring date: 03, 10, 20, 26 July 2023 (Daytime)

03&04, 10&11, 20&21, 26&27 July 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
03 July 2023	13:44	-	14:14	Sunny	57.7	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124528)
03 July 2023	19:29	-	19:34	Fine	55.1	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124528)
	20:19	-	20:24	Fine	51.8		
	21:19	-	21:24	Fine	52.7		
04 July 2023	1:24	-	1:29	Fine	50.5	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124528)
	3:34	-	3:39	Fine	53.1		
	5:24	-	5:29	Fine	53.0		
10 July 2023	13:25	-	13:55	Sunny	61.2	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124528)
10 July 2023	19:25	-	19:30	Fine	52.8	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124528)
	20:25	-	20:30		53.8		
	21:20	-	21:25		53.5		
11 July 2023	1:25	-	1:30	Fine	52.4	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124528)
	3:30	-	3:35		50.8		
	5:25	-	5:30		52.7		
20 July 2023	13:50	-	14:20	Sunny	58.2	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
20 July 2023	19:10	-	19:15	Fine	52.9	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:15	-	20:20		54.9		
	21:10	-	21:15		54.5		
21 July 2023	1:10	-	1:15	Fine	52.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:15	-	3:20		52.4		
	5:25	-	5:30		54.8		
26 July 2023	13:39	-	14:09	Sunny	63.9	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
26 July 2023	19:19	-	19:24	Fine	53.5	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:19	-	20:24		54.2		
	21:19	-	21:24		54.8		
27 July 2023	1:14	-	1:19	Fine	53.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:14	-	3:19		51.3		
	5:29	-	5:34		53.0		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N\_S2)

Monitoring date: 01, 07, 14, 21, 28 August 2023 (Daytime)

01&02, 07&08, 14&15, 21&22 and 28&29 August 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
01 Aug 2023	13:28	-	13:58	Fine	61.9	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
01 Aug 2023	19:08	-	19:13	Fine	54.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:13	-	20:18		54.7		
	21:13	-	21:18		54.9		
02 Aug 2023	1:13	-	1:18	Fine	52.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:28	-	3:33		51.5		
	5:18	-	5:23		54.6		
07 Aug 2023	13:53	-	14:23	Cloudy	58.7	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
07 Aug 2023	19:08	-	19:13	Fine	56.5	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:18	-	20:23		56.1		
	21:28	-	21:33		55.6		
08 Aug 2023	1:13	-	1:18	Fine	52.9	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:38	-	3:43		51.9		
	5:08	-	5:13		52.9		
14 Aug 2023	14:00	-	14:30	Fine	57.2	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
14 Aug 2023	19:25	-	19:30	Fine	53.7	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:15	-	20:20		54.0		
	21:15	-	21:20		54.9		
15 Aug 2023	1:15	-	1:20	Fine	52.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:05	-	3:10		49.5		
	5:10	-	5:15		52.0		
21 Aug 2023	14:53	-	15:23	Fine	60.2	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
22 Aug 2023	19:08	-	19:13	Fine	54.4	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:23	-	20:28		55.0		
	21:08	-	21:13		56.7		
22 Aug 2023	1:13	-	1:18	Fine	52.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:18	-	3:23		52.7		
	5:18	-	5:23		53.9		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b>L<sub>eq 30min</sub> dB(A) / L<sub>eq 5min</sub> dB(A)</b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
28 Aug 2023	13:43	-	14:13	Sunny	62.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
28 Aug 2023	19:13	-	19:18	Fine	54.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:23	-	20:28		54.8		
	21:28	-	21:33		56.0		
29 Aug 2023	1:13	-	1:18	Fine	53.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:18	-	3:23		51.7		
	5:18	-	5:23		54.5		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N\_S2)

Monitoring date: 06, 15, 19, 25 September 2023 (Daytime)

06&15, 15&16, 19&20 and 25&26 September 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Sep 2023	14:21	-	14:51	Cloudy	56.0	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
06 Sep 2023	19:16	-	19:21	Fine	58.2	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:26	-	20:31		51.8		
	21:16	-	21:21		51.9		
07 Sep 2023	1:36	-	1:41	Fine	51.0	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:46	-	3:51		51.7		
	5:31	-	5:36		52.4		
15 Sep 2023	13:31	-	14:01	Cloudy	57.4	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
15 Sep 2023	19:16	-	19:21	Fine	53.2	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:16	-	20:21		55.3		
	20:51	-	20:56		57.1		
16 Sep 2023	1:31	-	1:36	Fine	49.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:16	-	3:21		48.7		
	5:16	-	5:21		50.8		
19 Sep 2023	13:31	-	14:01	Sunny	61.4	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
19 Sep 2023	19:31	-	19:36	Fine	53.7	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:16	-	20:21		52.1		
	22:16	-	22:21		49.7		
20 Sep 2023	1:11	-	1:16	Fine	48.6	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:31	-	3:36		48.0		
	5:21	-	5:26		49.1		
25 Sep 2023	13:54	-	14:24	Sunny	57.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
25 Sep 2023	19:39	-	19:44	Fine	50.4	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	20:24	-	20:29		55.5		
	21:09	-	21:14		52.2		
26 Sep 2023	1:29	-	1:34	Fine	47.9	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.35124528)
	3:14	-	3:19		48.6		
	5:19	-	5:24		47.8		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N\_S3)

Monitoring date: 03, 10, 20, 26 July 2023 (Daytime)

03&04, 10&11, 20&21, 26&27 July 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
03 July 2023	13:30	-	14:00	Sunny	58.1	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
03 July 2023	19:30	-	19:35	Fine	54.5	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:20	-	20:25		53.8		
	21:20	-	21:25		50.2		
04 July 2023	1:25	-	1:30	Fine	49.1	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:30	-	3:35		51.3		
	5:20	-	5:25		49.2		
10 July 2023	13:21	-	13:51	Sunny	60.1	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
10 July 2023	19:31	-	19:36	Fine	54.6	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	20:26	-	20:31		53.9		
	21:26	-	21:31		53.4		
11 July 2023	1:26	-	1:31	Fine	51.6	SVAN 971 (Serial No. C132260)	Rion NC-75 (No.35124528)
	3:31	-	3:36		51.3		
	5:21	-	5:26		48.8		
20 July 2023	14:02	-	14:32	Sunny	57.5	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
20 July 2023	19:12	-	19:17	Fine	55.7	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:17	-	20:22		57.0		
	21:12	-	21:17		53.3		
21 July 2023	1:12	-	1:17	Fine	52.1	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:22	-	3:27		51.0		
	5:27	-	5:32		51.9		
26 July 2023	13:47	-	14:17	Sunny	62.8	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
26 July 2023	19:22	-	19:27	Fine	57.7	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:17	-	20:22		56.0		
	21:17	-	21:22		56.5		
27 July 2023	1:12	-	1:17	Fine	56.6	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:22	-	3:27		52.8		
	5:32	-	5:37		49.3		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N\_S3)

Monitoring date: 01, 07, 14, 21, 28 August 2023 (Daytime)

01&02, 07&08, 14&15, 21&22 and 28&29 August 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
01 Aug 2023	13:40	-	14:10	Fine	60.5	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
01 Aug 2023	19:10	-	19:15	Fine	56.7	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:15	-	20:20		57.8		
	21:10	-	21:15		56.4		
02 Aug 2023	1:10	-	1:15	Fine	45.5	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:25	-	3:30		47.2		
	5:15	-	5:20		47.8		
07 Aug 2023	13:53	-	14:23	Cloudy	63.3	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
07 Aug 2023	19:08	-	19:13	Fine	53.0	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:18	-	20:23		53.8		
	21:28	-	21:33		53.0		
09 Aug 2023	1:13	-	1:18	Fine	50.3	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:38	-	3:43		45.8		
	5:08	-	5:13		44.5		
14 Aug 2023	13:45	-	14:15	Fine	57.3	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
14 Aug 2023	19:20	-	19:25	Fine	51.8	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:10	-	20:15		50.3		
	21:25	-	21:30		50.8		
15 Aug 2023	1:25	-	1:30	Fine	45.9	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:15	-	3:20		45.9		
	5:20	-	5:25		46.6		
21 Aug 2023	14:43	-	15:13	Fine	55.8	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
22 Aug 2023	19:08	-	19:13	Fine	53.6	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:28	-	20:33		47.0		
	21:13	-	21:18		48.2		
22 Aug 2023	1:18	-	1:23	Fine	47.3	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:23	-	3:28		48.3		
	5:28	-	5:33		52.7		

<b>Date</b>	<b>Start time</b>		<b>End time</b>	<b>Weather</b>	<b><math>L_{eq\ 30min\ dB(A)} / L_{eq\ 5min\ dB(A)}</math></b>	<b>Sound Level Meter Used</b>	<b>Calibrator Used</b>
28 Aug 2023	13:59	-	14:29	Sunny	58.1	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
28 Aug 2023	19:19	-	19:24	Fine	53.0	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:24	-	20:29		54.9		
	21:29	-	21:34		48.7		
29 Aug 2023	1:14	-	1:19	Fine	44.5	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:19	-	3:24		44.3		
	5:19	-	5:24		50.9		



Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N\_S3)

Monitoring date: 06, 15, 20, 25 September 2023 (Daytime)

06&15, 15&16, 20&21 and 25&26 September 2023 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner

Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Sep 2023	14:29	-	14:59	Cloudy	57.8	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
06 Sep 2023	19:19	-	19:24	Fine	51.3	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:24	-	20:29		53.7		
	21:14	-	21:19		46.9		
07 Sep 2023	1:34	-	1:39	Fine	47.2	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:44	-	3:49		46.0		
	5:34	-	5:39		53.7		
15 Sep 2023	13:18	-	13:48	Cloudy	64.3	SVAN 971 (Serial No. C132269)	Rion NC-75 (No.35124528)
15 Sep 2023	19:13	-	19:18	Fine	54.4	SVAN 971 (Serial No. C132269)	Rion NC-75 (No.35124528)
	20:13	-	20:18		54.9		
	20:58	-	21:03		45.9		
16 Sep 2023	1:33	-	1:38	Fine	44.4	SVAN 971 (Serial No. C132269)	Rion NC-75 (No.35124528)
	3:18	-	3:23		41.8		
	5:13	-	5:18		47.4		
20 Sep 2023	13:42	-	14:12	Sunny	59.1	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124528)
20 Sep 2023	19:12	-	19:17	Fine	55.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124528)
	20:32	-	20:37		53.7		
	22:17	-	22:22		44.0		
21 Sep 2023	1:12	-	1:17	Fine	42.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124528)
	3:32	-	3:37		41.1		
	5:22	-	5:27		43.0		
25 Sep 2023	13:38	-	14:08	Sunny	59.1	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
25 Sep 2023	19:38	-	19:43	Fine	56.4	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	20:18	-	20:23		53.5		
	21:13	-	21:18		48.8		
26 Sep 2023	1:28	-	1:33	Fine	48.1	SVAN 971 (Serial No. C132261)	Rion NC-75 (No.35124528)
	3:13	-	3:18		50.9		
	5:18	-	5:23		47.9		