

## Appendix J Noise Monitoring Data

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N\_S1)

Monitoring date: 05, 13, 19, 26 September 2022 (Daytime)

05&06, 13&14, 19&20, 26&27 September 2022 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than Nil  
construction activities from  
the Project:

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
05 Sep 2022	13:07	-	13:37	Sunny	61.1	SVAN 971 (Serial No. 96063)	Svantek SV33B (No.83042)
05 Sep 2022	19:07	-	19:12	Fine	49.4	SVAN 971 (Serial No. 96063)	Svantek SV33B (No.83042)
	20:12	-	20:17		49.3		
	21:17	-	21:22		48.4		
06 Sep 2022	1:02	-	1:07	Fine	48.7	SVAN 971 (Serial No. 96063)	Svantek SV33B (No.83042)
	3:12	-	3:17		48.3		
	5:22	-	5:27		49.1		
13 Sep 2022	13:23	-	13:53	Sunny	63.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
13 Sep 2022	19:08	-	19:13	Fine	51.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:13	-	20:18		52.2		
	21:08	-	21:13		51.4		
14 Sep 2022	1:13	-	1:18	Fine	49.1	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:08	-	3:13		48.5		
	5:08	-	5:13		49.3		
19 Sep 2022	13:34	-	14:04	Sunny	63.5	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
19 Sep 2022	19:09	-	19:14	Fine	51.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:14	-	20:19		49.6		
	21:09	-	21:14		50.1		
20 Sep 2022	1:09	-	1:14	Fine	48.9	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:09	-	3:14		49.6		
	5:09	-	5:14		49.7		
26 Sep 2022	13:42	-	14:12	Sunny	65.5	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
26 Sep 2022	19:07	-	19:12	Fine	50.4	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
	20:12	-	20:17		50.2		
	21:02	-	21:07		50.4		
27 Sep 2022	1:17	-	1:22	Fine	48.6	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
	3:07	-	3:12		49.3		
	5:07	-	5:12		48.5		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N\_S2)

Monitoring date: 05, 13, 19, 29 September 2022 (Daytime)  
05&06, 13&14, 19&20, 29&30 September 2022 (Evening & Night time)

Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than Nil  
construction activities from  
the Project:

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
05 Sep 2022	13:20	-	13:50	Sunny	57.4	SVAN 971 (Serial No. 96062)	Svantek SV33B (No.83042)
05 Sep 2022	19:05	-	19:10	Fine	51.8	SVAN 971 (Serial No. 96062)	Svantek SV33B (No.83042)
	20:05	-	20:10		51.0		
	21:05	-	21:10		52.2		
06 Sep 2022	1:20	-	1:25	Fine	49.7	SVAN 971 (Serial No. 96062)	Svantek SV33B (No.83042)
	3:10	-	3:15		49.4		
	5:10	-	5:15		51.1		
13 Sep 2022	13:33	-	14:03	Sunny	60.2	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
13 Sep 2022	19:03	-	19:08	Fine	55.7	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
	20:03	-	20:08		55.6		
	21:08	-	21:13		54.6		
14 Sep 2022	1:13	-	1:18	Fine	52.7	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
	3:08	-	3:13		50.8		
	5:03	-	5:08		52.5		
19 Sep 2022	13:20	-	13:50	Sunny	60.4	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
19 Sep 2022	19:10	-	19:15	Fine	55.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:10	-	20:15		55.9		
	21:10	-	21:15		56.8		
20 Sep 2022	1:15	-	1:20	Fine	55.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:15	-	3:20		56.0		
	5:10	-	5:15		55.8		
29 Sep 2022	13:47	-	14:17	Sunny	63.1	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
29 Sep 2022	19:17	-	19:22	Fine	57.1	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:12	-	20:17		55.2		
	21:17	-	21:22		56.3		
30 Sep 2022	1:07	-	1:12	Fine	50.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:02	-	3:07		51.3		
	5:12	-	5:17		51.6		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N\_S3)

Monitoring date: 05, 13, 19, 26 September 2022 (Daytime)

05&06, 13&14, 19&20, 26&27 September 2022 (Evening & Night time)


Parameter :  $L_{eq\ 30min}$  (Daytime),  $L_{eq\ 5min}$  (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner


Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
05 Sep 2022	13:04	-	13:34	Sunny	61.2	SVAN 971 (Serial No. 103482)	Svantek SV33B (No.83042)
05 Sep 2022	19:09	-	19:14	Fine	55.8	SVAN 971 (Serial No. 103482)	Svantek SV33B (No.83042)
	20:04	-	20:09		53.3		
	21:19	-	21:24		48.9		
06 Sep 2022	1:14	-	1:19	Fine	49.6	SVAN 971 (Serial No. 103482)	Svantek SV33B (No.83042)
	3:19	-	3:24		47.0		
	5:09	-	5:14		48.5		
13 Sep 2022	13:18	-	13:48	Sunny	63.1	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
13 Sep 2022	19:08	-	19:13	Fine	52.9	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:03	-	20:08		53.7		
	21:08	-	21:13		53.2		
14 Sep 2022	1:18	-	1:23	Fine	46.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:13	-	3:18		47.1		
	5:13	-	5:18		47.1		
19 Sep 2022	13:35	-	14:05	Sunny	61.6	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
19 Sep 2022	19:10	-	19:15	Fine	55.8	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
	20:05	-	20:10		54.1		
	21:10	-	21:15		56.9		
20 Sep 2022	1:15	-	1:20	Fine	49.7	SVAN 971 (Serial No. 103482)	Rion NC-75 (No.34724244)
	3:10	-	3:15		51.2		
	5:10	-	5:15		49.2		
26 Sep 2022	13:39	-	14:09	Sunny	60.9	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
26 Sep 2022	19:14	-	19:19	Fine	46.4	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:09	-	20:14		47.5		
	21:04	-	21:09		51.3		
27 Sep 2022	1:09	-	1:14	Fine	56.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:09	-	3:14		53.8		
	5:19	-	5:24		54.6		

### Impact Noise Monitoring Results during Day Time (0700 - 1900 hours)



# Additional Impact Noise Monitoring Results during Evening Time (1900 - 2300 hours)



### Additional Impact Noise Monitoring Results during Night Time (2300 - 0700 hours)

