

Appendix J Noise Monitoring Data

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N_S1)

Monitoring date: 06, 16, 20, 27 March 2023 (Daytime)

06&07, 16&17, 20&21, 27&28 March 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Mar 2023	13:44	-	14:14	Sunny	61.9	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
06 Mar 2023	19:14	-	19:19	Fine	51.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:29	-	20:34		51.2		
	21:34	-	21:39		51.4		
07 Mar 2023	1:09	-	1:14	Fine	51.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:19	-	3:24		51.8		
	5:19	-	5:24		48.5		
16 Mar 2023	13:58	-	14:28	Sunny	59.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
16 Mar 2023	19:18	-	19:23	Fine	45.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:03	-	20:08		44.7		
	21:18	-	21:23		44.8		
17 Mar 2023	1:28	-	1:33	Fine	45.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:23	-	3:28		50.9		
	5:18	-	5:23		51.0		
20 Mar 2023	13:36	-	14:06	Fine	61.1	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
20 Mar 2023	19:11	-	19:16	Fine	48.4	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:06	-	20:11		48.3		
	21:26	-	21:31		48.6		
21 Mar 2023	1:26	-	1:31	Cloudy	46.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:26	-	3:31		46.1		
	5:26	-	5:31		48.2		
27 Mar 2023	13:35	-	14:05	Fine	58.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
27 Mar 2023	19:20	-	19:25	Fine	46.2	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	20:20	-	20:25		42.6		
	21:10	-	21:15		43.6		
28 Mar 2023	1:15	-	1:20	Fine	39.7	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.34724244)
	3:25	-	3:30		40.3		
	5:20	-	5:25		40.9		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N_S2)

Monitoring date: 06, 16, 20, 27 March 2023 (Daytime)

06&07, 16&17, 20&21, 27&28 March 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Mar 2023	13:49	-	14:19	Sunny	57.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
06 Mar 2023	19:14	-	19:19	Fine	52.1	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	20:29	-	20:34		53.7		
	21:24	-	21:29		51.6		
07 Mar 2023	1:14	-	1:19	Fine	51.2	SVAN 971 (Serial No. C119577)	Rion NC-75 (No.34724244)
	3:24	-	3:29		51.3		
	5:24	-	5:29		49.4		
16 Mar 2023	13:40	-	14:10	Sunny	57.1	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
16 Mar 2023	19:15	-	19:20	Fine	51.0	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	20:05	-	20:10		50.3		
	21:15	-	21:20		50.8		
17 Mar 2023	1:20	-	1:25	Fine	49.4	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	3:25	-	3:30		51.0		
	5:25	-	5:30		49.7		
20 Mar 2023	13:47	-	14:17	Fine	56.7	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
20 Mar 2023	19:12	-	19:17	Fine	50.5	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	20:07	-	20:12		49.4		
	21:27	-	21:32		50.3		
21 Mar 2023	1:27	-	1:32	Cloudy	48.9	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	3:27	-	3:32		48.7		
	5:27	-	5:32		48.6		
27 Mar 2023	13:42	-	14:12	Fine	57.5	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
27 Mar 2023	19:22	-	19:27	Fine	50.7	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	20:22	-	20:27		50.0		
	21:07	-	21:12		49.6		
28 Mar 2023	1:12	-	1:17	Fine	49.6	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.34724244)
	3:27	-	3:32		49.7		
	5:22	-	5:27		49.7		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N_S3)

Monitoring date: 06, 16, 20, 27 March 2023 (Daytime)

06&07, 16&17, 20&21, 27&28 March 2023 (Evening & Night time)


Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Air-conditioner


Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
06 Mar 2023	13:43	-	14:13	Sunny	57.9	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
06 Mar 2023	19:13	-	19:18	Fine	46.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:28	-	20:33		47.5		
	21:33	-	21:38		46.9		
07 Mar 2023	1:13	-	1:18	Fine	47.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:03	-	3:08		47.3		
	5:08	-	5:13		43.6		
16 Mar 2023	13:33	-	14:03	Sunny	54.6	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
16 Mar 2023	19:13	-	19:18	Fine	45.1	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:08	-	20:13		42.0		
	21:23	-	21:28		41.3		
17 Mar 2023	1:18	-	1:23	Fine	45.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:18	-	3:23		48.1		
	5:18	-	5:23		44.3		
20 Mar 2023	13:02	-	13:32	Fine	54.8	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
20 Mar 2023	19:07	-	19:12	Fine	46.4	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:07	-	20:12		44.7		
	21:27	-	21:32		49.0		
21 Mar 2023	1:22	-	1:27	Cloudy	43.3	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:12	-	3:17		39.5		
	5:07	-	5:12		43.3		
27 Mar 2023	13:38	-	14:08	Fine	59.2	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
27 Mar 2023	19:23	-	19:28	Fine	44.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	20:23	-	20:28		43.6		
	21:23	-	21:28		40.6		
28 Mar 2023	1:18	-	1:23	Fine	43.4	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.34724244)
	3:23	-	3:28		45.9		
	5:23	-	5:28		46.3		

Impact Noise Monitoring Results during Day Time (0700 - 1900 hours)



Additional Impact Noise Monitoring Results during Evening Time (1900 - 2300 hours)



Additional Impact Noise Monitoring Results during Night Time (2300 - 0700 hours)

