

Appendix G Noise Monitoring Data

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 1 (M1 / N_S1)

Monitoring date: 10, 13, 20, 29 November 2023 (Daytime)
 10&11, 13&14, 20&21 and 29&30 November 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
10 Nov 2023	13:33	-	14:03	Sunny	57.8	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
10 Nov 2023	19:08	-	19:13	Fine	51.8	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	20:08	-	20:13		53.9		
	21:08	-	21:13		52.3		
11 Nov 2023	1:08	-	1:13	Fine	46.6	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	3:08	-	3:13		45.0		
	5:08	-	5:13		45.1		
13 Nov 2023	13:42	-	14:12	Sunny	56.3	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
13 Nov 2023	19:12	-	19:17	Fine	47.5	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	20:12	-	20:17		53.9		
	21:07	-	21:12		45.3		
14 Nov 2023	1:07	-	1:12	Fine	44.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	3:07	-	3:12		43.2		
	5:12	-	5:17		44.3		
20 Nov 2023	13:57	-	14:27	Sunny	63.2	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
20 Nov 2023	19:12	-	19:17	Fine	47.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	20:27	-	20:32		46.1		
	21:17	-	21:22		45.3		
21 Nov 2023	1:17	-	1:22	Fine	41.0	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	3:17	-	3:22		41.1		
	5:17	-	5:22		40.2		
29 Nov 2023	13:50	-	14:20	Cloudy	60.1	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
29 Nov 2023	19:10	-	19:15	Fine	50.4	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	20:25	-	20:30		43.0		
	21:30	-	21:35		42.7		
30 Nov 2023	1:10	-	1:15	Fine	41.2	SVAN 971 (Serial No. 96062)	Rion NC-75 (No.35124527)
	3:15	-	3:20		42.2		
	5:20	-	5:25		40.2		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 2 (M2 / N_S2)

Monitoring date: 10, 13, 20, 29 November 2023 (Daytime)

10&11, 13&14, 20&21 and 29&30 November 2023 (Evening & Night time)

Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Nil

Noise Monitoring Data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
10 Nov 2023	13:39	-	14:09	Sunny	57.2	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
10 Nov 2023	19:09	-	19:14	Fine	51.6	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	20:09	-	20:14		49.3		
	21:09	-	21:14		48.0		
11 Nov 2023	1:09	-	1:14	Fine	47.0	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	3:09	-	3:14		45.6		
	5:09	-	5:14		47.3		
13 Nov 2023	13:21	-	13:51	Sunny	56.6	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
13 Nov 2023	19:16	-	19:21	Fine	49.9	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	20:06	-	20:11		49.7		
	21:01	-	21:06		49.6		
14 Nov 2023	1:06	-	1:11	Fine	46.3	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	3:06	-	3:11		49.0		
	5:31	-	5:36		48.0		
20 Nov 2023	13:54	-	14:24	Sunny	62.3	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
20 Nov 2023	19:14	-	19:19	Fine	48.3	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	20:04	-	20:09		53.2		
	21:19	-	21:24		49.3		
21 Nov 2023	1:14	-	1:19	Fine	45.3	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	3:14	-	3:19		45.4		
	5:24	-	5:29		45.2		
29 Nov 2023	13:32	-	14:02	Cloudy	57.8	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
29 Nov 2023	19:07	-	19:12	Fine	51.0	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	20:12	-	20:17		49.6		
	21:17	-	21:22		47.7		
30 Nov 2023	1:12	-	1:17	Fine	44.4	SVAN 971 (Serial No. 103449)	Rion NC-75 (No.35124527)
	3:07	-	3:12		43.3		
	5:02	-	5:07		43.5		

Location: Shek Kwu Chau Treatment & Rehabilitation Centre Hostel 3 (M3 / N_S3)

Monitoring date: 10, 13, 20, 29 November 2023 (Daytime)

10&11, 13&14, 20&21 and 29&30 November 2023 (Evening & Night time)


Parameter : $L_{eq\ 30min}$ (Daytime), $L_{eq\ 5min}$ (Evening & Night time)

Noise source other than construction activities from the Project: Construction works of air quality monitoring station


Noise Monitoring data:

Date	Start time		End time	Weather	$L_{eq\ 30min}$ dB(A) / $L_{eq\ 5min}$ dB(A)	Sound Level Meter Used	Calibrator Used
10 Nov 2023	16:30	-	17:00	Sunny	54.6	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
10 Nov 2023	19:10	-	19:15	Fine	52.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	20:05	-	20:10		48.4		
	21:15	-	21:20		49.6		
11 Nov 2023	1:10	-	1:15	Fine	46.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	3:20	-	3:25		48.3		
	5:05	-	5:10		46.6		
13 Nov 2023	16:05	-	16:35	Sunny	57.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
13 Nov 2023	19:10	-	19:15	Fine	44.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	20:05	-	20:10		44.3		
	21:25	-	21:30		45.8		
14 Nov 2023	1:20	-	1:25	Fine	43.6	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	3:20	-	3:25		43.8		
	5:20	-	5:25		44.0		
20 Nov 2023	16:46	-	17:16	Sunny	54.8	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
20 Nov 2023	19:21	-	19:26	Fine	47.9	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	20:11	-	20:16		48.4		
	21:31	-	21:36		42.6		
21 Nov 2023	1:06	-	1:11	Fine	46.0	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	3:21	-	3:26		40.2		
	5:11	-	5:16		41.5		
29 Nov 2023	14:45	-	15:15	Cloudy	58.6	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
29 Nov 2023	19:10	-	19:15	Fine	45.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	20:15	-	20:20		47.1		
	21:20	-	21:25		44.3		
30 Nov 2023	1:15	-	1:20	Fine	42.7	SVAN 971 (Serial No. 96063)	Rion NC-75 (No.35124527)
	3:10	-	3:15		41.8		
	5:15	-	5:20		43.6		

Impact Noise Monitoring Results during Day Time (0700 - 1900 hours)



Additional Impact Noise Monitoring Results during Evening Time (1900 - 2300 hours)



Additional Impact Noise Monitoring Results during Night Time (2300 - 0700 hours)

